

∗1 : Before Aug. 2008 Production
∗2 : From Aug. 2008 Production
Headlight Beam Level Control
Power Source
1
2
3
4
H10
Headlamp Leveling Motor (LH)
H11
Headlamp Leveling Motor (RH)
H14
Headlamp Leveling SW
J 1
Junction Connector
J 5(A), J 6(B)
Junction Connector
J 3(A), J 4(B)
Junction Connector
Left Side of the Fender Apron
Right Side of the Fender Apron
C12
Combination SW
Light Control SW
T1
B1
OFF
Tail
Head
10A TAIL
100A ALT
Battery
R–W
(∗2)
R–W
(∗1)
G
G–W
W–B
L–O(∗1)
L–O(∗2)
R–W(∗1)
R–W(∗2)
B
W